



Actually plotted IF over-all response curve of the receiver owned by the Author. The slight assymetry is probably caused by a detuned roofing filter (the circuit has not been trimmed since almost half a century ago...).